



Service Advisory

TAT SA 12-01

Issued: 12/02/10

Model SR22 w/ Turbonormalizer

Installed per STC SA10588SC

And SE10589SC

TO: Owners, Operators, and Service Centers

SUBJECT: Release of Hartzell Engine Technologies Service Bulletin No. 040

EFFECTIVITY: Cirrus Design SR22 equipped with a Tornado Alley Turbo Inc. Turbonormalizing System using Hartzell Engine Technologies (Formerly Kelly Aerospace) **Turbochargers**. Any aircraft or engine utilizing new (-0000 series) or rebuilt (-9000 series), turbochargers, manufactured before serial number H-NJL00003 (new) or H-NJR00002 (rebuilt).

Vendor Contact	Hartzell Engine Technologies Technical Support 1-888-461-6077
Document Number	Service Bulletin No. 040
Date	11/9/10
Subject	Debris found in center housing rotating assemblies (CHRA)
Description	This Service Bulletin is being issued to mandate the cleaning of CHRA center housing of turbochargers according to (HET) Service Bulletin No.040
Compliance	Mandatory: Hartzell Engine Technologies
MANPOWER	One mechanic.

WARRANTY INFORMATION Reference Hartzell Engine Technologies Technical Service Bulletin No. 040